

Michael O. Leavitt

Governor

State of Uta DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT



1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax)

Lowell P. Braxton Division Director

801-538-7223 (TDD)

Partial: xxx Complete: Exploration:

Inspection Date & Time: 10/27/99 / 10:30A.M.-2:00P.M.

Date of Last Inspection: 9/28/99

Mine Name: Centennial Project County: Carbon Permit Number: ACT/007/019						
Permittee and/or Operator's Name: Andalex Resources, Inc.						
Business Address: P.O. Box 902, Price, Utah 84501						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Mike Glasson						
State Officials(s): Peter Hess Federal Official(s): None						
Weather Conditions: Clear, Cool, 30's						
Existing Acreage: Permitted-5063 Disturbed-34 Regraded-0 Seeded-0 Bonded-34						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/Temporary Cessation/Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For <u>partial inspections</u> check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2. 3.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOIL	EVALUATED [_] [XX] [XX]	<u>N/A</u> ∐ ∐ ∐	COMMENTS [XX] 	NOV/ENF
4. a. b. c. d.	HYDROLOGIC BALANCE: DIVERSIONS SEDIMENT PONDS AND IMPOUNDMENTS OTHER SEDIMENT CONTROL MEASURES WATER MONITORING EFFLUENT LIMITATIONS	[XX] [XX] [XX] [_]		[XX] [XX] []	
5. 6. 7. 8.	EXPLOSIVES DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS NONCOAL WASTE PROTECTION OF FISH, WILDLIFE AND				
10. 11. 12. 13. 14. 15.	RELATED ENVIRONMENTAL VALUES SLIDES AND OTHER DAMAGE CONTEMPORANEOUS RECLAMATION BACKFILLING AND GRADING REVEGETATION SUBSIDENCE CONTROL CESSATION OF OPERATIONS ROADS:		[] [XX] [XX] [XX] [XX] [XX]		
a.	CONSTRUCTION/MAINTENANCE/SURFACING DRAINAGE CONTROLS OTHER TRANSPORTATION FACILITIES SUPPORT FACILITIES/UTILITY INSTALLATIONS AVS CHECK (4th Quarter-April, May, June)(date) AIR QUALITY PERMIT BONDING & INSURANCE	[XX] [XX] [XX] []			

INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: 10/27/99

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS

It was suggested that the permittee identification sign which is approximately 200 feet up-canyon from the powder and cap magazines (as shown on Plate 6 of the Centennial MRP) be moved down the canyon to where the disturbed area perimeter is shown on Plate 6. The disturbed area perimeter is approximately 30 feet up-canyon from the powder storage magazine.

4a. HYDROLOGIC BALANCE: DIVERSIONS

Two erosion gullies have developed 200 feet NNW of the Pinnacle Mine truck loadout; these need to be repaired. The berm, which should prevent this outslope flow from developing, needs to be repaired.

A ditch has been cut by erosion directly east of the Pinnacle Mine truck loadout. Flow in this ditch converges with flow in ditch DD-2, thence into the 18-inch culvert which flows to catch basin B-4. Mr. Glasson would prefer to add this ditch to the surface drainage map, rather than repair the damage, and then have future flows re-cut the area.

A review of Plate 8, Support Facilities Surface Drainage Area shows a designated ditch DD-9 on the west side of the Apex Mine truck loading loop. Surface personnel have placed numerous pieces of machinery in this flow path obstructing it. Mr. Glasson was instructed to have the machinery pulled back and have the ditch redefined according to design specification in the MRP.

The discharge end of culvert CD-8 needs cleaning.

The ditch on the west side of primary road #2, (PR-2) has had flows which have eroded around the concrete energy dissipaters which the permittee has installed, rendering them ineffective. The ditch needs work to repair this erosion.

Several other ditches were observed, and in general most of them needed some form of maintenance.

4c. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The straw bales, which were installed in diversion ditch UD-3 (as shown on Plate 6) to control sediment flow into the main Canyon undisturbed bypass culvert, need maintenance to make them effective. Most of the channel has developed some vegetation.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: 10/27/99

(Comments are Numbered to Correspond with Topics Listed Above)

8. NONCOAL WASTE

The site has numerous empty 55-gallon barrels stored about. Some contained longwall makeup emulsion; some are Rok-Lok barrels (yellow and green). At least 44 empty emulsion barrels were counted in the Apex Mine area. This is more than a mine should conservatively be able to use. Mr. Glasson agreed to have the barrels disposed of, or returned to the manufacturer.

Copy of this Report:

Mailed to: Mike Glasson (Andalex)

Given to: Pam Grubaugh-Littig (DOGM)

Date: November 1, 1999

Inspector's Signature: #46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Peter Hess